













Proposed Improvements

- 01 Retain existing mature trees
- 02 New kerb ramp to improve access
- 03 Park entry improvements with bench seat, bubbler and park sign
- 04 Native palm grove and understorey plantings
- 05 New brick retaining and seating wall
- 06 Additional understorey low shrub plantings
- 07 New sandstone or brick paving
- 08 Open turf grass areas for passive recreation
- 09 Additional border shrubs and climber plantings
- 10 New boundary screen fence to improve privacy and park amenity
- 11 Repair to existing brick retaining wall
- 12 New low park fence and handrail
- 13 Existing stairs

Key

- | | | | | | |
|--|--------------------------------------|---|--|---|---|
|  | Existing trees to be retained |  | Sandstone or brick paving |  | New 900mm high painted park fence |
|  | New advanced native palms |  | New low brick retaining & seating wall |  | 1.8m high painted palisade screen fence |
|  | 2 trees in poor health to be removed |  | Timbers bench seats |  | Park sign |
|  | Low shrub and groundcovers |  | New water bubbler with dog bowl | | |
|  | Turf Grass | | | | |

