












Proposed Improvements

- | | |
|---|--|
| 01 Existing trees to be retained | 07 Cliff stabilisation & sandstone wall repairs |
| 02 New kerb ramp to improve access | 08 Feature lighting to sandstone cliff & wall |
| 03 Existing timber platform & stairs to be removed | 09 New link path to improve access, safety & circulation. |
| 04 New infill palisade fence panel | 10 Existing brick and stone play cubbies to be retained |
| 05 Rearrange seats to improve safety and use and more seats | 11 Repairs to existing palisade fence |
| 06 New accessible barbeque & table | 12 Raised lawn terrace for passive recreation & to increase soil depth |

- | |
|--|
| 13 New platform bench |
| 14 New park path lights to improve night-time safety |
| 15 Nature & imaginative play space with maritime rope, balance beam & pole |
| 16 New multi-play structure with steps, decks, servery, climb challenge, tunnel & slides |
| 17 New double swing with toddler cradle & seat |
| 18 New accessible link path |

Key

- | | | | |
|---|-------------------------------|---|---------------------------------|
|  | Existing trees to be retained |  | Park Lights |
|  | New shade tree |  | Timbers bench seats |
|  | Low shrub and groundcovers |  | Park sign |
|  | Turf Grass |  | New water bubbler with dog bowl |
|  | Sandstone or brick paving |  | Garbage Bin |
|  | Organic softfall mulch | | |
|  | Rubber softfall mulch surface | | |

 **NORTH**
August 2021